

# Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.  
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

**DATE OF THIS VERSION (new)**

June 1, 2014

**TITLE OF DOCUMENT (new title if applicable):**

Copper Standing Seam Roofing, 07 61 16

**DATE OF VERSION BEING SUPERSEDED (old):**

April 22, 2010

**DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):**

Batten Seam Sheet Metal Roofing, 07 61 16

**SUMMARY OF CHANGES IN THIS VERSION:**

1. Dates of Applicable Publications have been updated to reflect current editions.
2. Section checked and confirmed to comply with Section 508 of the Rehabilitation Act of 1973.
3. Part 1 reference to new Division 1 Section 01 81 11 "Sustainable Design Requirements" added.
4. Added provision for Pre-Installation Conference.
5. Modified the section to specify standing seam copper field-fabricated roofing instead of batten seam roofing.