

ELECTRICAL SYMBOLS - POWER PLAN



STARTER OR MOTOR CONTROLLER

\$#

SWITCH

F = FUSED SWITCH

L = LOCK

M = MANUAL MOTOR STARTING

MP= MOTOR SNAP WITH PILOT LIGHT
(THERMAL TYPE)

PB= PUSH BUTTON STATION

WP= WEATHER PROOF

K = KEY OPERATED

LM= LOW VOLTAGE MASTER

MC= MOMENTARY CONTACT

P = WITH PILOT LIGHT

RC= REMOTE CONTROL

X = EXPLOSION PROOF

VA



U.S. Department
of Veterans Affairs

DETAIL TITLE / ELECTRICAL SYMBOLS-POWER PLAN

SCALE: NONE

DATE ISSUED: JULY 1, 2020

CAD DETAIL NO.:

SD260511-11.DWG